





The flood and gales brought down trees and undercut the banks particularly on the lower section.




Bank Badly undermined
and boulders, both natural and inserted moved.







Proposals at Point G.



Path and Track at point “I”.

